

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer : Aswini.T
2. Name of the School : Hill View International School
3. Location with name of Education District / Sub.District : Koodathai Bazar  
: Thamarassery Education District
4. Classification of Building as specified in column 4 of the Application for fitness certificate and size. : RCC framed structure  
5 (6.90\*6.90\*3.75 m) GF (Circular Rooms)  
2 (7.00\*5.80\*3.75 m) GF (Semi Elliptical Rooms)  
5 (6.90\*6.90\*3.75 m) FF (Circular Rooms)  
2 (7.00\*5.80\*3.75 m) FF (Semi Elliptical Rooms)  
  
Permenant multi storied Building
5. Period for which the certificate is issued : :2022-23
6. Nature of defects,if and
  - a) Foundation and basement : Nil
  - b) Super structure : Nil
  - c) Doors and Windows : Nil
  - d) Wood work wrought and put up : Nil
  - e) Roof : Nil
  - f) Flooring : Nil
  - g) Miscellaneous (Cracks,etc.) : Nil
7. Any major defects noticed which will render the Building unsafe in any manner : No
8. Whether maintenance works have beend one properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound under normal weather and wind conditions

**Note :1. The stability of the structure should be examined also with reference to location altitude , intensity of wind, exposure of flood etc.**


**2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.**

## CERTIFICATE

Certified that the school building was inspected by me on 09.12.2022 and found to be fit to conduct classes for the period 2022-23 for the reasons stated above.

Place : Omassery

Date: 09.12.2022



Assistant Engineer

ASSISTANT ENGINEER  
PWD & EW  
SECTION OMASSERY